

00VDPN9 FR12023-01-05 ŠIJANEC63230317as82306 @

Mealyjev avtomat, podan s tabelo prelojanja stanj, pretvorite v Mooreov avtomat. Mooreov avtomat pritažite tabelarično in grafično.

	S_0	S_1	S_2	S_3
X_1	S_1/z_2	S_1/z_2	S_1/z_2	S_1/z_2
X_2	S_3/z_1	S_0/z_0	S_3/z_1	S_2/z_1

	z_0	z_2	z_1	z_1
	S_{00}	S_{12}	S_{21}	S_{31}
X_1	S_{12}	S_{12}	S_{12}	S_{12}
X_2	S_{31}	S_{00}	S_{31}	S_{21}

$$X_{M0} = \{X_1, X_2\}$$

$$Z_{M0} = \{z_0, z_1, z_2\}$$

$$S_{M0} = \{S_{00}, S_{12}, S_{21}, S_{31}\}$$



